

**SECRET**

(When Filled In)

FILE INFO

3372

REPRODUCTION PROHIBITED

ACTION	1	DM	6	11	16
	2		7	12	17
	3		8	13	18
25X1A	4		9	14	19
	5		10	15	20

NNNS F C R E I 12 5452 NOV 71 CITE

25X1A

IDEALIST/DY-3

SUBJ: PRE-CONDITIONING CART

25X1A

FROM:

25X1A 1. DURING RECENT VISIT TO 133SRW/OL TO A SIMILAR PROBLEM TO THAT INDICATED IN PARA TWO OF REF. MESSAGE WAS ENCOUNTERED ON THE INITIAL CART TO VEHICLE HOOK UP USING THE BLANKET. ONCE THE BLANKET HAD BEEN PLACED ON THE VEHICLE IT WAS IMMEDIATELY SECURED IN PLACE USING THE ATTACHED STRAPS. WHEN DIFFICULTY WAS EXPERIENCED IN CONNECTING CART AIR IN AND OUT HOSES THE BLANKET SECURITY STRAPS WERE UNFASTENED, ALLOWING THE BLANKET TO HANG FREELY. THROUGH REPOSITIONING THE BLANKET AROUND AIR IN AND AIR OUT CONNECTOR PORTS BOTH HOSE CONNECTIONS WERE ACCOMPLISHED WITHOUT ENCOUNTERING FURTHER DIFFICULTY. THIS PROCEDURE HAS BEEN USED ONCE SINCE ON A CREW TRAINING EXERCISE WITHOUT DIFFICULTY BEING EXPERIENCED IN CART HOSE CONNECTIONS.

25X1A 2. TRUSTS THAT ABOVE INFO MAY BE HELPFUL.

**SECRET**